

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Inspection Information

Shop Name:IHR-Technika s.r.o.

Address:Boleslavska 902 Kosmonosy Na Radouci 1221 Mlada Boleslav Kosmonosy
Czech Republic

Zip Code:29306

Telephone:+420 326 722 716

Email:info@ihr-tech.cz

SN:985692109800

Test Time:2024-03-07 10:13:33

Technician Name:Fleischhans

Customer Name:Rezutka



Vehicle Information

Make:Jaguar

VIN:SAJAA28R9CMV21037

Odometer:128623 km

Vehicle Software Version:V33.70

Diagnostic Application Version:V7.00.031

Diagnostic path:Automatically Search > Health Report

System fault code

The following system is abnormal:

ECM (Engine Control Module) 3 problems exist

- | | |
|--|--------------|
| 1.P0172-00 System too rich (bank 1) | Intermittent |
| 2.P0175-00 System too rich (bank 2) | Intermittent |
| 3.P0430-00 Catalyst system efficiency below threshold (bank 2) | Intermittent |

IPC (Instrument Cluster Control Module) 1 problem exist

- | | |
|----------------|--------------|
| 1.B12FE-13 Fan | Intermittent |
|----------------|--------------|

BCM (Body Control Module) 1 problem exist

- | | |
|----------------------|--------------|
| 1.B1087-88 LIN bus A | Intermittent |
|----------------------|--------------|

HCM (Headlamp Control Module) 1 problem exist

- | | |
|--|--------------|
| 1.U3002-81 Vehicle identification number | Intermittent |
|--|--------------|

PBM (Parking Brake Control Module) 1 problem exist

1.U0415-00 Invalid data received from ABS control module Intermittent

SCME (Driver's Climate Seat Module) 1 problem exist

1.U0140-00 Lost communication with body control module Intermittent

FCDIM (Front Control/display Interface Module(high Level Display Front)) 1 problem exist

1.B1D21-13 Remote control switch Intermittent

RFA (Keyless Vehicle Module) 2 problems exist

1.U201F-31 External receiver Intermittent

2.U2100-00 Initial configuration is not complete. Historic

SCMF (Rear Differential Control Module) 2 problems exist

1.U0140-00 Lost communication with body control module Intermittent

2.U0156-00 Lost communication with information center A Intermittent

ACM (Audio Front Control Module) 1 problem exist

1.B1D55-13 Antenna 2 circuit Intermittent

REM (Rear Entertainment Control Module) 1 problem exist

1.U3003-62 Battery voltage Intermittent

TVM (Television Module) 2 problems exist

1.B1A56-13 Antenna circuit Intermittent

2.B1D55-13 Antenna 2 circuit Intermittent

The following systems are OK:

1.TCM (Transmission Control Module)

2.ABS (Anti-lock Braking System)

3.SRS (Supplemental Inflatable Restraint System)

4.RLM (Ride Level Control Module)

5.GSM (Gear Shift Module)

6.SUMB (Adaptive Damping Control Module)

7.CCM (Speed Control Module)

8.RDCM (Rear Differential Control Module)

9.VIM (Vehicle Immobilizer Control Module)

10.DDM (Driver's Door Module)

11.DSM (Driver's Seat Module)

12.FCIMB (Front Controls Interface Module B(front Audio Control Panel))

13.HCMB (Headlamp Control Module B)

14.HVAC (Heating Ventilation And Air Conditioning Control Module)

15.PAM (Parking Assist Control Module)

16.PDM (Passenger's Door Module)

- 17.PSM (Passenger's Seat Module)
- 18.RGTM (Rear Gate/trunk Module)
- 19.RHVAC (Rear Heating Ventilation And Air Conditioning Control Module)
- 20.RRSM (Rear Right - Seat Module)
- 21.RLSM (Rear Left - Seat Module)
- 22.SODL (Side Object Detection Control Module-Left)
- 23.SODR (Side Object Detection Control Module-Right)
- 24.AAM (Audio Amplifier Module)
- 25.DABM (Digital Audio Broadcast Module)