Diagnosis report
Date: 04.05.2020 15:20

Customer:		**Cartype:**	BMW X6 E71/E72 (X6) (2008 – 2014)
Customer No.:		**VIN:**	L199275
License plate:		**Mileage:**	km

Engine electronics (MSD80 6Z N53/N54)

Identification:

Hardware number: 7437af
Diagnostic index: 0
Control unit Producer: Siemens
Operating software: 0.0.0
AVL-ECU-ID: 8636-3982-0

Hardware version: 0
Version index: 16689
Message catalogue: ff.ff.ff
VIN: L199275

Codification index: 18
Manufacturing date: 2008.11.24
Function software: 0.0.0
Serial number: 083150081

Error Codes:

Error code	Error description
[29D1] 10705	**Engine misfiring cylinder 5**
	Error test cycle fully run through
	Sporadic error
	Error would cause the illumination of a malfunction indicator lamp
[29D2] 10706	**Engine misfiring cylinder 6**
	Error test cycle fully run through
	Sporadic error
	Error would cause the illumination of a malfunction indicator lamp
[29D0] 10704	**Engine misfiring, cylinder 4**
	Error test cycle fully run through
	Sporadic error
	Error would cause the illumination of a malfunction indicator lamp
[29DC] 10716	**Cylinder injection shutoff**
	Error test cycle fully run through
	Sporadic error
	Error would cause no illumination of a malfunction indicator lamp

Remarks:

Inspector:

Signature: