

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Inspection Information

Shop Name:IHR-Technika s.r.o.

Address:Boleslavska 902 Kosmonosy Na Radouci 1221 Mlada Boleslav Kosmonosy
Czech Republic

Zip Code:29306

Telephone:+420 326 722 716

Email:info@ihr-tech.cz

SN:985692109800

Test Time:2022-12-28 09:18:20

Technician Name:Kratky

Customer Name:Mares Jiri

Notes:Mares Jiri



Vehicle Information

License #:6L24232

Make:Toyota

VIN:JTMZC31V90D014935

Odometer:145671

Vehicle Software Version:V49.53

Diagnostic Application Version:V7.00.031

Diagnostic path:16PIN DLC(Europe and Other) > 2012.12-2015.10,2AD-FTV > w/ Smart Key > MT

Notes:Mares Jiri

System fault code

The following system is abnormal:

Engine and ECT 3 problems exist

1.P2002 Particulate Trap Efficiency Below Threshold(Bank 1)	Current
2.P2002 Particulate Trap Efficiency Below Threshold(Bank 1)	History
3.P2002 Particulate Trap Efficiency Below Threshold(Bank 1)	Pending

ABS/VSC/TRC 1 problem exist

1.C1201 Engine Control System Malfunction	Current
---	---------

Air Conditioner 2 problems exist

1.B1421 Solar Sensor Circuit(Passenger Side)	Current
--	---------

2.B1424 Solar Sensor Circuit(Driver Side)

Current

The following systems are OK:

- 1.Cruise Control
- 2.EMPS
- 3.Combination Meter
- 4.Main Body
- 5.D-Door Motor
- 6.Entry&Start