

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Inspection Information

Shop Name:IHR-Technika s.r.o.

Address:Boleslavska 902 Kosmonosy Na Radouci 1221 Mlada Boleslav Kosmonosy
Czech Republic

Zip Code:29306

Telephone:+420 326 722 716

Email:info@ihr-tech.cz

SN:985692109800

Test Time:2023-05-31 15:27:48

Technician Name:Fleischhans

Customer Name:Syrucek



Vehicle Information

Make:Skoda

VIN:TMBJH7NP1G7031660

Odometer:438011 km

Vehicle Software Version:V28.20

Diagnostic Application Version:V7.00.031

Diagnostic path:Health Report

System fault code

The following system is abnormal:

01 Engine Control Module 1 3 problems exist

1.P029900 Turbo/Super Charger Underboost	passive/abiogenesis
2.P029900 Turbo/Super Charger Underboost	passive/abiogenesis
3.P032200 Ign. /Distributor Eng. Speed Inp. Circ. -No Signal	passive/abiogenesis

03 Brakes 1 2 problems exist

1.U112300 Databus Error Value Received	passive/abiogenesis
2.U112300 Databus Error Value Received	passive/abiogenesis

08 Air Conditioning 2 problems exist

1.B10AF04 Air Quality Sensor - Faulty	active/static
2.B109171 Front Air Distribution Door Motor - Actuator Jammed	active/static

09 Central Electrics 1 problem exist

1.B12ECF2 Left Daytime Running Lamp And Parking Lamp LED Module - Supply, Open Circuit/short Circuit To B+ passive/abiogenesis

13 Adaptive Cruise Control 5 problems exist

1.U112300 Databus Error Value Received passive/abiogenesis

2.U112300 Databus Error Value Received passive/abiogenesis

3.U112300 Databus Error Value Received passive/abiogenesis

4.U112200 Data Bus Implausible Message passive/abiogenesis

5.U112300 Databus Error Value Received passive/abiogenesis

19 Gateway 1 problem exist

1.U010000 Lost Communication With ECM/PCM passive/abiogenesis

2B Steering Column Locking 1 problem exist

1.U112300 Databus Error Value Received passive/abiogenesis

36 Seat Adjustment Driver Side 3 problems exist

1.B135654 Seat Backrest Adjustment Motor - No Basic Setting active/static

2.B135354 Seat Angle Adjustment Motor - No Basic Setting active/static

3.B201000 No Basic Setting active/static

76 Parking Assistance 1 problem exist

1.U112300 Databus Error Value Received passive/abiogenesis

A5 Front Sensors Driver Assistance System 1 problem exist

1.U112300 Databus Error Value Received passive/abiogenesis

B7 Access Startsystem Interface 1 problem exist

1.U112300 Databus Error Value Received passive/abiogenesis

The following systems are OK:

1.15 Airbag

2.16 Steering Column Electronics

3.17 Dash Board

4.42 Door Electronics Driver Side

5.44 Steering Assistance

6.52 Door Electronics Passenger Side

7.55 Headlight Regulation

8.5F Information Control Unit 1