

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Inspection Information

Shop Name:IHR-Technika s.r.o.

Address:Boleslavska 902 Kosmonosy Na Radouci 1221 Mlada Boleslav Kosmonosy
Czech Republic

Zip Code:29306

Telephone:+420 326 722 716

Email:info@ihr-tech.cz

SN:985692109800

Test Time:2023-06-07 10:06:53

Technician Name:Fleischhans

Customer Name:Floder

Notes:Clutch faulty, Misfires



Vehicle Information

License #:4E66823

Make:Seat

VIN:VSSZZZ6JZAR080613

Odometer:188050 km

Vehicle Software Version:V28.15

Diagnostic Application Version:V7.00.031

Diagnostic path:Health Report

Notes:Clutch faulty, Misfires

System fault code

The following system is abnormal:

01 Engine Control Module 1 5 problems exist

1.P262600 O2 Sensor Pumping Current Trim Circuit/Open Bank 1, active/static
Sensor 1

2.P030300 Cyl.3-Misfire Detected

passive/abiogenesis

3.P030200 Cyl.2-Misfire Detected

passive/abiogenesis

4.P130A00 Hide Cylinder

passive/abiogenesis

5.P030000 Random/Multiple Cylinder - Misfire Detected

passive/abiogenesis

02 Transmission Control Module 2 problems exist

1.P177B Clutch 1 : Tolerance Limit Reached

Mechanical Failure

2.P1898 Clutch 1 : Function Restriction

56 Radio 1 problem exist

1.03138 Input AUX IN

Open Circuit

The following systems are OK:

1.03 Brakes 1

2.08 Air Conditioning

3.09 Central Electrics

4.15 Airbag

5.17 Dash Board

6.19 Gateway

7.25 Immobilizer

8.2E Media Player Position 3

9.4B Multifunction Module

10.77 Telephone