

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Inspection Information

Shop Name:IHR-Technika s.r.o.

Address:Boleslavska 902 Kosmonosy Na Radouci 1221 Mlada Boleslav Kosmonosy
Czech Republic

Zip Code:29306

Telephone:+420 326 722 716

Email:info@ihr-tech.cz

SN:985692109800

Test Time:2024-08-21 14:42:17

Technician Name:Fleischhans

Customer Name:Sumovsky

Notes:DPF Monitoring



Vehicle Information

License #:5AT1905

Make:BMW

VIN:WBAKS410X00H66942

Odometer:258823 km

Vehicle Software Version:V50.51

Diagnostic Application Version:V7.00.031

Diagnostic path:Automatically Search > System Selection > Drive > ECM (Engine Control Module - DME/DDE)

Notes:DPF Monitoring

DTC

| DTC | Description | State |
|--------|--|--------------|
| 287500 | Oxygen Sensor Before Catalytic Converter, Signal: Too Low The Event Of Coasting Overrun | Intermittent |
| 287100 | Oxygen Sensor Before Catalytic Converter, Signal: Too High For Partial Load | Permanent |